

Neropoxy HB Coating 6061

Scope

Neropoxy HB Coating 6061 is a two pack high build epoxy polyamide cured matt paint. This paint is designed to use as an intermediate & topcoat in most of epoxy systems. It has good resistance against water & splash of mild chemicals. It can be recoated with epoxy, polyurethane, chlorinated rubber and conventional coating. As in all epoxies, the product chalks on weathering which results fading. The product may show the brush marks when applied by brush.

Composition

Epoxy resin suitably pigmented & separately packed clear polyamide solution as hardener.

Volume solids	65 ± 3%
DFT / Coat	60 – 125 μ
Theoretical Coverage / Coat	5.20 - 10.80 m ² /ltr.

Product Details

Type	Two Pack
Mixing Ratio	By volume
Component A	13 parts
Component B	1 part
Colour	Light & Dark Grey.
Gloss	Matt
Pot Life	4 – 6 Hrs. at 30°C
Curing Mechanism	Solvent release and chemical reaction between the components
Flash Point	
Component A	Above 25°C
Component B	Above 25°C
Recoating Time	Min.18 Hrs. Max.1month provided surface is dry-clean & free from any contaminants. After max. over coating interval the surface should be roughened prior to application of subsequent coat.
Drying Time (30°C)	
Surface Dry	2 – 3 Hrs.
Hard Dry	16 – 18 Hrs.
Full Cure	7 Days
Thinner	T-353
Thinner Consumption	
Conventional Spray	25 – 35%
Brush	10 – 15%

Application Details

Applied over:

Epoxy Primer, undercoat / Zinc Primer

Application Method:

Brush / Airless spray / Conventional spray

Shelf Life:

12 months under normal storage condition in original sealed containers at 30°C

Pack Size:

4 ltrs. & 20 ltrs.

Surface Preparation:

Recommended to use on Zinc Primer epoxy primer or epoxy undercoat. Before applying this epoxy coating, the primed surface must be clean, dry & free from moisture, grease and other contaminants. In case of aged epoxy primer, the surface should be sufficiently roughened prior to painting.

Application Instruction:

Stir the Comp.A and Comp.B separately. If settling is observed in the component A, loosen the settled material & mix it with the help of pneumatic stirrer. Mix component B gradually into the component A in the specified ratio under continuous stirring till homogeneous. Use Epoxy thinner(T-353) as specified.

Environmental Conditions:

Surface temperature must be at least 3°C above Dew Point to prevent condensation.

Temperature:

Air	5 - 40°C
Surface	5 - 50°C

Special Notes:

Thinner consumption may vary depending upon site conditions. Practical covering capacity depends on application techniques, ambient conditions, wastage, surface condition etc.

Safety Precautions:

Please refer to the Material Safety Data Sheet.

Kansai Nerolac Paints (KNP) warrants the goods to be free from defects in material and workmanship. KNP makes no other warranties concerning the goods. No other warranties, whether expressed, implied or statutory, such as warranties of merchantability or fitness for a particular purpose, shall apply to goods and in no event shall KNP be liable for consequential or incidental damages. Any recommendation or suggestion relating to use of the products made by KNP whether in the technical literature of KNP, or in response to specific inquiry, or otherwise, is based on data believed to be reliable by KNP, and KNP shall not be liable for any loss or damage incurred to the Buyer on account thereof. However, the goods and information are intended for use by the Buyer having requisite skill and know-how in the industry, and therefore it is for the Buyer to satisfy himself of the suitability of the goods for his own particular use and it shall be deemed that the Buyer has done so, at his sole discretion and risk. Variation in environment, changes in procedures of use, or extrapolation of data may cause unsatisfactory results".

Issue Date: October 15, 2006

PN: 2553-8